

root@bosque-TX: /tmp/verification

8	1	308452352	sda1
8	2	1	sda2
8	5	4116480	sda5
8	16	3997696	sdb
8	17	3997568	sdb1
8	32	3997696	sdc
8	33	3997568	sdc1

root@bosque-TX:~# mkdir -p /mnt/usb

root@bosque-TX:~# mount /dev/sdb1 /mnt/usb

root@bosque-TX:~# cd /mnt/usb

root@bosque-TX:/mnt/usb# bash ./DS200-SetupDirectory.sh

cp: omitting directory '/mnt/usb/DS200'

cp: omitting directory '/mnt/usb/output'

Creation of temporary verification directory is complete.

root@bosque-TX:/mnt/usb# cd /tmp/verification

root@bosque-TX:/tmp/verification# ./DS200-LoadExportFiles.sh sdc

Firmware Export files have been loaded.

root@bosque-TX:/tmp/verification# ./DS200-VerifyHash.sh DS200-DS0314350039

diff: HashTrusted-DS200.txt: No such file or directory

DS200 firmware matches Trusted Hash File.

Hash File, DS200-DS0314350039_Hash.txt, copied to output

root@bosque-TX:/tmp/verification#